

The differences of software version between the product tested and the product proposed are shown in next table. Only "System Files" and "Data" versions are different because it is caused by different product name.

	NP-NC1402L+	NP-NC1202L+	NP-NC1202L
<b>DCCv2 Version</b>	3.4.0.91		
<b>Projector Information</b>			
<b>System</b>	NC1402L+	NC1202L+	NC1202L
<b>Network</b>			
<b>IP Address</b>	192.168.10.10 / 255.255.255.0		
<b>Gateway</b>	0.0.0.0		
<b>Satellite</b>			
<b>Red</b>	2xLVDS		
<b>Green</b>	2xLVDS		
<b>Blue</b>	2xLVDS		
<b>DMD</b>	0.69" DC2K		
<b>Version</b>			
<b>FMT</b>			
<b>FMT CPU</b>			
<b>U-Boot</b>	Mar 02 2016 env1.004		
<b>Kernel</b>	Mar 2 2016 rfs1.0.1		
<b>System Files</b>	0.070	0.071	
<b>Main Software</b>	0.01.007		
<b>Data</b>	1.060	1.061	
<b>ICP Main Software</b>	4.05 (43)		
<b>ICP Config File</b>	1.002		
<b>Secure Processor</b>			
<b>Main Firmware</b>	27		
<b>FMT FPGA</b>			
<b>ICP Main Firmware</b>	4.01 (84)		
<b>FMT Main Software</b>	5.40 (14)		
<b>FMT Main Firmware</b>	4.54 (14)		
<b>Satellite Firmware</b>	1.02 (45)		
<b>Sequence File</b>	1.00 (6)		
<b>DMD File</b>	0.02 (17)		
<b>Slave CPU</b>			
<b>Slave BIOS</b>	1.01.002		
<b>Slave Firmware</b>	1.03.006		
<b>SLAVE</b>			
<b>Opt-MCU Firmware</b>	ME13		
<b>LD Interface</b>			
<b>LU Firmware</b>	5		
<b>LD Driver</b>			
<b>1</b>	24		
<b>2</b>	24		
<b>3</b>	24		
<b>4</b>	24	NA	
<b>Lens Firmware</b>	STPN_E06		